S – Satisfactory U – Unsatisfactory N/A – Not Applicable N/ $\hat{C}$  – Not Checked If an item is marked U, N/A, or N/C, an explanation must be included in this report.

A completed **Standard Inspection Checklist, Cover Letter and Field Report** is to be submitted to the Chief Engineer within 30 days from completion of the inspection.

|                                       |     | Inspection Report                     |                     |           |       |
|---------------------------------------|-----|---------------------------------------|---------------------|-----------|-------|
| Inspection ID/Docket number           | •   | ID 6784                               |                     |           |       |
| Inspector Name & Submit Date          |     | Anthony Dorrough – July 1, 2016       |                     |           |       |
| Chief Eng Name & Review Date          |     | Joe Subsits, July 6, 2016             |                     |           |       |
|                                       |     | Operator Information                  |                     |           |       |
| Name of Operator:                     | We  | eyerhaeuser Company - Longview        |                     | OP ID #:  | 22515 |
| Name of Unit(s):                      | We  | eyerhaeuser – Ostrander               |                     |           |       |
| <b>Records Location:</b> 34           |     | 01 Industrial Way, Longview WA, 98632 |                     |           |       |
| Date(s) of Last (unit)<br>Inspection: | 6/2 | 4-25/2013                             | Inspection Date(s): | 6/1-2/201 | 6     |

#### **Inspection Summary:**

#### Historical Data

The Weyerhaeuser-Ostrander Pipeline is comprised of 4 (NPS-4) (~1000ft) and 12-inch diameter (NPS-12) (~9miles), API 5L, X-42 ERW steel pipe with the 12 inch diameter sections having a nominal wall thickness of 0.25 inches for below ground sections and 0.5 nominal wall thickness for above ground sections. The company operates the natural gas transmission pipeline in Cowlitz County, Washington beginning at the Williams Pipeline Interconnection slightly north east of the City of Kelso and ending at the Longview Facility. Weyerhaeuser purchased CNG's district regular station and uses it to control the gas to NorPac. The 4-inch line also can send gas to Solvay.

On March 1, 2010, Weyerhaeuser became part of Cosentino Consultant Corp's Total Care Program. This means that the consultant will visit site every 90 days; has review plan for each visit to ensure all requirements are met and appropriate forms filled out. Also, he will be emailed about every gas function, etc...

Weyerhaeuser also has the designs for automatic shutoff valves done and other measures for mitigation in response to PHMSA's ANPRM Docket 2011-0023.

There was [1] probable violation noted for this inspection

#### CFR 192.615 Emergency Plans

- (b) Each operator shall:
- (2) Train the appropriate operating personnel to assure that they are knowledgeable of the emergency procedures and verify that the training is effective.

#### Finding:

A records review revealed that Weyerhaeuser could not provide documentation to support any emergency procedure training, or verification of the effectiveness of any emergency procedure training, i.e drills. (NOPV)

| HQ Address:                       |                                   |  | System/Unit Name & Add      | lress:         |  |  |  |
|-----------------------------------|-----------------------------------|--|-----------------------------|----------------|--|--|--|
| Weyerhaeuser Compa                | any                               |  | N/A                         |                |  |  |  |
| 3401 Industrial Way               |                                   |  |                             |                |  |  |  |
| Longview WA, 98632                |                                   |  |                             |                |  |  |  |
| P.O. Box 188<br>Longview, WA 9863 | 32                                |  |                             |                |  |  |  |
| Co. Official:                     |                                   | chnitger                                   | Phone No.:                  |                |  |  |  |
| Phone No.:                        | Stephano Schnitger (360) 636-6812 |  | Fax No.:                    |                |  |  |  |
| Fax No.:                          | (360) 578-4                       |  | <b>Emergency Phone No.:</b> |                |  |  |  |
| Emergency Phone No.:              | (360) 636-6                       |  |                             |                |  |  |  |
| Persons Intervi                   | ` /                               |  | itle                        | Phone No.      |  |  |  |
| Robert L. Cosentino               |                                   | President & CEO, Cosentino Consulting Inc. |                             | (360) 200-4959 |  |  |  |
|                                   |                                   |  |                             |                |  |  |  |
|                                   |                                   |  |                             |                |  |  |  |
|                                   |                                   |  |                             |                |  |  |  |

|   | UTC staff conducted abbreviated procedures inspection on 192 O&M and WAC items that changed since the last inspection. This checklist focuses on Records and Field items per a routine standard inspection. |       |              |
|---|---|-------|--------------|
|   | (check one below and enter appropriate date)  |       |              |
| X | Team inspection was performed (Within the past five years.) or,   | Date: | 6/24-25 2013 |
|   | Other UTC Inspector reviewed the O & M Manual (Since the last yearly review of the manual by the operator.)   | Date: |              |

|   |      | GAS SYST  | TEM OPERATIONS   |   |
|---|------|---|--|---|
| Gas Suppl   | lier | Williams Gas Pipeline                               |  |   |
| Number of reportable safety related conditions last year 0            |      | able safety related conditions last year 0          | Number of deferred leaks in syste  | em 0  |
| Number of <u>non-reportable</u> safety related conditions last year 0 |      | eportable safety related conditions last year 0     | Number of third party hits last ye   | ar 0  |
| Miles of tr   |      | sion pipeline within unit (total miles and miles in |  |   |
| Operating Pressure(s):  |      | Operating Pressure(s):                              | MAOP (Within last year)  | Actual Operating Pressure (At time of Inspection) |
| Feeder:   | 688p | osig  | 2009 Hydro established the MAOP of the Weyerhaeuser-Ostrander Pipeline @ 706psig per. the O&M Hydrostatic Test Rating = (1060) / (1.5) Hydrostatic Test Rating = 706psig | 249psig   |
| Town:   |      |   |  |   |
| Other:  |      |   |  |   |

S – Satisfactory U – Unsatisfactory N/A – Not Applicable N/C – Not Checked If an item is marked U, N/A, or N/C, an explanation must be included in this report.

| GAS SYSTEM OPERATIONS                              |     |  |
|--|-----|--|
| Does the operator have any transmission pipelines? | YES |  |
| Compressor stations? Use Attachment 4.             | NO  |  |

| Pipe Specifications:   |                               |                              |                                   |
|------------------------|-------------------------------|------------------------------|-----------------------------------|
| Year Installed (Range) | 1992                          | Pipe Diameters (Range)       | NPS-12 / NPS-4                    |
| Material Type          | X-42 ERW                      | Line Pipe Specification Used | API 5L                            |
| Mileage                | 9 Miles NPS-12 / 1000ft NPS-4 | SMYS %                       | 42.9 @ time of inspection         |
| Supply Company         | Geneva Steel (records in IMP  | Class Locations              | Entire line is considered Class-3 |
|                        | manual)                       |                              |                                   |

#### **Integrity Management Field Validation**

**Important:** Per PHMSA, IMP Field Verification Form 16 (Rev 6/18/2012) shall be used by the inspector as part of this standard inspection. When completed, the inspector will upload this information into the PHMSA IM Database (IMDB) located at http://primis.phmsa.dot.gov/gasimp/home.gim **Date Uploaded:** XXXXXXXXXX

| PART 199 DRUG at | nd ALCOHOL TESTING REGULATIONS and PROCEDURES   | S | U | NA | NC |
|------------------|---|---|---|----|----|
| Subparts A - C   | Drug & Alcohol Testing & Misuse Prevention Program – Use PHMSA Form #13, Rev 3/19/2010. Do not ask the company to have a drug and alcohol expert available for this portion of your inspection. | X |   |    |    |

| PART 192 Im | plement Applicable Control Room Management Procedures   | S | U | NA | NC |
|-------------|---|---|---|----|----|
| .605(b)(12) | Implementing the applicable control room management procedures required by 192.631. (Amdt. 192- 112, 74 FR 63310, December 3, 2009, eff. 2/1/2010)No control room |   |   | X  |    |

|    |   | REPORTING RECORDS   | S | U | N/A | N/C |
|----|---|---|---|---|-----|-----|
| 1. | 49 U.S.C. 60132,<br>Subsection (b)<br>ADB-08-07 | Submission of Data to the National Pipeline Mapping System Under the Pipeline Safety Improvement Act of 2002 – January 18, 2016  Updates to NMPS: Operators are required to make update submissions every 12 months if any system modifications have occurred. Go to <a href="http://www.npms.phmsa.dot.gov/submission/">http://www.npms.phmsa.dot.gov/submission/</a> to review existing data on record. Also report no modifications if none have occurred since the last complete submission. Include operator contact information with all updatesUpdate sent in Jan 2016 to NPMS via email | X |   |     |     |
| 2. | RCW 81.88.080                                   | Pipeline Mapping System: Has the operator provided accurate maps (or updates) of pipelines, operating over two hundred fifty pounds per square inch gauge, to specifications developed by the commission sufficient to meet the needs of first responders?Yes –Apr 2012   | X |   |     |     |
| 3. | 191.5   | Immediate Notice of certain incidents to NRC (800) 424-8802, or electronically at <a href="http://www.nrc.uscg.mil/nrchp.html">http://www.nrc.uscg.mil/nrchp.html</a> , and additional report if significant new information becomes available.   |   |   | X   |     |
| 4. | 191.7   | Reports (except SRCR and offshore pipeline condition reports) submitted electronically to PHMSA at <a href="http://portal.phmsa.dot.gov/pipeline">http://portal.phmsa.dot.gov/pipeline</a> unless an alternative reporting method is authorized IAW with paragraph (d) of this section.   |   |   | X   |     |
| 5. | 191.15(a)                                       | Do records indicate reportable <u>incidents</u> were identified and reports were submitted to DOT on Form 7100.2 (01-2002) within the required timeframe?   |   |   | X   |     |
| 6. | 191.15(c)                                       | Do records indicate accurate supplemental incident reports were filed and within the required timeframe?  |   |   | X   |     |
| 7. | 191.17  | Complete and submit DOT Form PHMSA F 7100-2.1 by March 15 of each calendar year for the preceding year. ( <i>NOTE: June 15, 2013 for the year 2012</i> )Checked Jan 2016 submission   | X |   |     |     |

|     |   | REPORTING RECORDS   | S | U | N/A | N/C |
|-----|---|---|---|---|-----|-----|
| 8.  | 191.22  | Each operator must obtain an OPID, validate its OPIDs, and notify PHMSA of certain events at <a href="http://portal.phmsa.dot.gov/pipeline">http://portal.phmsa.dot.gov/pipeline</a> OPID 22515   | X |   |     |     |
| 9.  | 191.23  | Have complete and accurate Annual Reports been submitted? Checked 2013, 14, 15  | X |   |     |     |
| 10. | 191.25<br>49 U.S.C. 60139,<br>Subsection (b)(2) | Filing the SRCR within 5 days of determination, but not later than 10 days after discovery.  Note: Operators of gas transmission pipelines that if the pipeline pressure exceeds maximum allowable operating pressure (MAOP) plus the build-up, owner/operator must report the exceedance to PHMSA on or before the fifth day following the date on which the exceedance occurs.  The report should be titled "Gas Transmission MAOP Exceedance" and provide the following information:  • The name and principal address of the operator, date of the report, name, job title, and business telephone number of the person submitting the report.  • The name, job title, and business telephone number of the person who determined the condition exists.  • The date the condition was discovered and the date the condition was first determined to exist.  • The location of the condition, with reference to the town/city/county and state or offshore site, and as appropriate, nearest street address, offshore platform, survey station number, milepost, landmark, and the name of the commodity transported or stored.  The corrective action taken before the report was submitted and the planned follow-up or future corrective action, including the anticipated schedule for starting and concluding such actionNone |   |   | X   |     |
| 11. | 191.27(a), (b)                                  | Do records indicate reports were submitted within 60 days of completing inspections of underwater pipelines?  |   |   | X   |     |
| 12. | 192.727(g)                                      | Do records indicate reports were filed for abandoned offshore pipeline facilities or abandoned onshore pipeline facilities that crosses over, under or through a commercially navigable waterway?   |   |   | X   |     |
| 13. | 480-93-200(1)                                   | Telephonic Reports to UTC Pipeline Safety Incident Notification 1-888-321-9144 (Within 2 hours) for events which (regardless of cause);   |   |   | X   |     |
| 14. | 480-93-200(1)(a)                                | Result in a fatality or personal injury requiring hospitalization;  |   |   | X   |     |
| 15. | 480-93-200(1)(b)                                | Results in damage to property of the operator and others of a combined total exceeding fifty thousand dollars;  Note: Report all damages regardless if claim was filed with pipeline company or not.  |   |   | X   |     |
| 16. | 480-93-200(1)(c)                                | Results in the evacuation of a building, or high occupancy structures or areas;   |   |   | X   |     |
| 17. | 480-93-200(1)(d)                                | Results in the unintentional ignition of gas;   |   |   | X   |     |
| 18. | 480-93-200(1)(e)                                | Results in the unscheduled interruption of service furnished by any operator to twenty five or more distribution customers;   |   |   | X   |     |
| 19. | 480-93-200(1)(f)                                | Results in a pipeline or system pressure exceeding the MAOP plus ten percent or the maximum pressure allowed by proximity considerations outlined in WAC 480-93-020;  |   |   | X   |     |
| 20. | 480-93-200(1)(g)                                | Is significant, in the judgment of the operator, even though it does not meet the criteria of (a) through (e) of this subsection; or  |   |   | X   |     |
| 21. | 480-93-200(2)                                   | Telephonic Reports to UTC Pipeline Safety Incident Notification 1-888-321-9146 (Within 24 hours) for;   |   |   | X   |     |
| 22. | 480-93-200(2)(a)                                | The uncontrolled release of gas for more than two hours;  |   |   | X   |     |
| 23. | 480-93-200(2)(b)                                | The taking of a high pressure supply or transmission pipeline or a major distribution supply pipeline out of service;   |   |   | X   |     |
| 24. | 480-93-200(2)(c)                                | A pipeline operating at low pressure dropping below the safe operating conditions of attached appliances and gas equipment; or  |   |   | X   |     |
| 25. | 480-93-200(2)(d)                                | A pipeline pressure exceeding the MAOP  |   |   | X   |     |

|                     | or stored.   |   |
|---------------------|--|---|
|                     | The corrective action taken before the report was submitted and the planned follow-up or   |   |
|                     |  |   |
|                     |  |   |
| 191.27(a), (b)      |  |   |
| 1,511.27 (11), (10) | * *  | 78  |
| 100 505( )          |  | <b>X</b> 7  |
| 192.727(g)          |  | X   |
|                     |  |   |
| 480-93-200(1)       |  | X   |
| 480-93-200(1)(a)    |  | X   |
| 400 75 200(1)(u)    |  | 21  |
| 480-93-200(1)(b)    |  |   |
| 400 75 200(1)(0)    | , and the second |   |
| 480-93-200(1)(c)    | Results in the evacuation of a building, or high occupancy structures or areas;  | X   |
| 480-93-200(1)(d)    | Results in the unintentional ignition of gas;  | X   |
| 400.02.200/11//     | Results in the unscheduled interruption of service furnished by any operator to twenty five  | <b>T</b> 7  |
| 480-93-200(1)(e)    | or more distribution customers;  | X   |
| 490 02 200(1)(f)    | Results in a pipeline or system pressure exceeding the MAOP plus ten percent or the  | X   |
| 480-93-200(1)(1)    | maximum pressure allowed by proximity considerations outlined in WAC 480-93-020;   | Λ   |
| 480-93-200(1)(g)    |  | $\mathbf{X}$  |
| 400-73-200(1)(g)    |  | Λ   |
| 480-93-200(2)       |  | $\mathbf{X}$  |
|                     |  |   |
| 480-93-200(2)(a)    | The uncontrolled release of gas for more than two hours;   | X   |
| 480 03 200(2)(b)    | The taking of a high pressure supply or transmission pipeline or a major distribution supply   | X   |
| 460-93-200(2)(0)    |  | Λ   |
| 480-93-200(2)(c)    |  | X   |
| +00 73 200(2)(c)    | attached appliances and gas equipment; or  |   |
|                     | A pipeline pressure exceeding the MAOP   |   |
|                     | 480-93-200(1)(a)<br>480-93-200(1)(b)<br>480-93-200(1)(c)<br>480-93-200(1)(d)<br>480-93-200(1)(e)<br>480-93-200(1)(f)<br>480-93-200(2)(a)<br>480-93-200(2)(b)   | future corrective action, including the anticipated schedule for starting and concluding such actionNone  191.27(a), (b)  Do records indicate reports were submitted within 60 days of completing inspections of underwater pipelines?  Do records indicate reports were filed for abandoned offshore pipeline facilities or abandoned onshore pipeline facilities that crosses over, under or through a commercially navigable waterway?  Telephonic Reports to UTC Pipeline Safety Incident Notification 1-888-321-9144 (Within 2 hours) for events which (regardless of cause);  Result in a fatality or personal injury requiring hospitalization;  Results in damage to property of the operator and others of a combined total exceeding fifty thousand dollars;  Note: Report all damages regardless if claim was filed with pipeline company or not.  Results in the evacuation of a building, or high occupancy structures or areas;  Results in the unintentional ignition of gas;  Results in the unscheduled interruption of service furnished by any operator to twenty five or more distribution customers;  Results in a pipeline or system pressure exceeding the MAOP plus ten percent or the maximum pressure allowed by proximity considerations outlined in WAC 480-93-020;  18 significant, in the judgment of the operator, even though it does not meet the criteria of (a) through (e) of this subsection; or  Telephonic Reports to UTC Pipeline Safety Incident Notification 1-888-321-9146 (Within 24 hours) for;  The taking of a high pressure supply or transmission pipeline or a major distribution supply pipeline out of service;  A pipeline operating at low pressure dropping below the safe operating conditions of |

S – Satisfactory U – Unsatisfactory N/A – Not Applicable N/C – Not Checked If an item is marked U, N/A, or N/C, an explanation must be included in this report.

| Q3 | thru   | Q6    | ·No rep | orting | records | s requi | red    |
|----|--------|-------|---------|--------|---------|---------|--------|
| Q1 | 1 thru | ı Q25 | No r    | eporti | ng reco | rds rec | quired |

| 26. | 480-93-200(5)    | Written incident reports (within 30 days) including the following;  | S | U | N/A | N/C |
|-----|------------------|---|---|---|-----|-----|
| 27. | 480-93-200(4)(a) | Name(s) and address(es) of any person or persons injured or killed, or whose property was damaged   |   |   | X   |     |
| 28. | 480-93-200(4)(b) | The extent of injuries and damage;  |   |   | X   |     |
| 29. | 480-93-200(4)(c) | A description of the incident or hazardous condition including the date, time, and place, and reason why the incident occurred. If more than one reportable condition arises from a single incident, each must be included in the report; |   |   | X   |     |
| 30. | 480-93-200(4)(d) | A description of the gas pipeline involved in the incident or hazardous condition, the system operating pressure at that time, and the MAOP of the facilities involved;   |   |   | X   |     |
| 31. | 480-93-200(4)(e) | The date and time the gas pipeline company was first notified of the incident;  |   |   | X   |     |
| 32. | 480-93-200(4)(f) | The date and time the ((operators')) gas pipeline company's first responders arrived on-site;   |   |   | X   |     |
| 33. | 480-93-200(4)(g) | The date and time the gas ((facility)) pipeline was made safe;  |   |   | X   |     |
| 34. | 480-93-200(4)(h) | The date, time, and type of any temporary or permanent repair that was made;  |   |   | X   |     |
| 35. | 480-93-200(4)(i) | The cost of the incident to the ((operator)) gas pipeline company;  |   |   | X   |     |
| 36. | 480-93-200(4)(j) | Line type;  |   |   | X   |     |
| 37. | 480-93-200(4)(k) | City and county of incident; and  |   |   | X   |     |
| 38. | 480-93-200(4)(1) | Any other information deemed necessary by the commission.   |   |   | X   |     |
| 39. | 480-93-200(5)    | Submit a supplemental report if required information becomes available  |   |   | X   |     |
| 40. | 480-93-200(6)    | Written report within 45 days of receiving the failure analysis of any <b>incident or</b> hazardous condition due to construction defects or material failure   |   |   | X   |     |

#### Q26 thru Q40 ---No reporting records required---

**Comments:** 

| 41. | 480-93-200(7)    | Filing Reports of Damage to Gas Pipeline Facilities to the commission. (eff 4/1/2013) (Via the commission's Virtual DIRT system or on-line damage reporting form)  |  |   |  |
|-----|------------------|--|--|---|--|
| 42. | 480-93-200(7)(a) | Does the operator report to the commission the requirements set forth in RCW 19.122.053(3) (a) through (n)   |  | X |  |
| 43. | 480-93-200(7)(b) | Does the operator report the name, address, and phone number of the person or entity that the company has reason to believe may have caused damage due to excavations conducted without facility locates first being completed?  |  | X |  |
| 44. | 480-93-200(7)(c) | Does the operator retain all damage and damage claim records it creates related to damage events reported under 93-200(7)(b), including photographs and documentation supporting the conclusion that a facilities locate was not completed?  Note: Records maintained for two years and made available to the commission upon request. |  | X |  |
| 45. | 480-93-200(8)    | Does the operator provide the following information to excavators who damage gas pipeline facilities?  |  |   |  |

S – Satisfactory U – Unsatisfactory N/A – Not Applicable N/C – Not Checked If an item is marked U, N/A, or N/C, an explanation must be included in this report.

| 46. | 480-93-200(8)(a)  | Notification requirements for excavators under RCW 19.122.050(1)  |   |   | X   |     |
|-----|-------------------|---|---|---|-----|-----|
| 47. | 480-93-200(8)(b)  | A description of the excavator's responsibilities for reporting damages under<br>RCW 19.122.053; and  |   |   | X   |     |
| 48. | 480-93-200(8)(c)  | <ul> <li>Information concerning the safety committee referenced under RCW 19.122.130,<br/>including committee contact information, and the process for filing a complaint<br/>with the safety committee.</li> </ul>   |   |   | X   |     |
| 49. | 480-93-200(9)     | Reports to the commission only when the operator or its contractor observes or becomes aware of the following activities  • An excavator digs within thirty-five feet of a transmission pipeline, as defined by RCW 19.122.020(26) without first obtaining a facilities locate; (200(9)(a)  • A person intentionally damages or removes marks indicating the location or presence of gas pipeline facilities. 200(9)(b) |   |   | X   |     |
| 50. | 480-93-200(7)     | Filing Reports of Damage to Gas Pipeline Facilities to the commission. (eff 4/1/2013) (Via the commission's Virtual DIRT system or on-line damage reporting form)   |   |   | X   |     |
| 51. | 480-93-200(10)    | <b>Annual Reports</b> filed with the commission no later than <b>March 15</b> for the proceeding calendar year. ( <i>NOTE: PHMSA extension to June 15, 2013 for the year 2012</i> ).  | S | U | N/A | N/C |
| 52. | 480-93-200(10)(a) | A copy of PHMSA F-7100.1-1 and F-7100.2-1 annual report required by U.S. Department of Transportation, PHMSA/Office of Pipeline Safety  | X |   |     |     |
| 53. | 480-93-200(10)(b) | Reports detailing all construction defects and material failures resulting in leakage.  Categorizing the different types of construction defects and material failures. The report must include the following:  (i) Types and numbers of construction defects; and  (ii) Types and numbers of material failuresNo Const. defect Reports required  |   |   | X   |     |
| 54. | 480-93-200(11)    | Providing updated emergency contact information to the commission and appropriate officials of all municipalities where gas pipeline companies have facilities  | X |   |     |     |
| 55. | 480-93-200(12)    | Providing by email, reports of daily construction and repair activities no later than 10:00 a.mHave 45-Day advance notice policy  | X |   |     |     |
| 56. | 480-93-200(13)    | Submitting copy of DOT Drug and Alcohol Testing MIS Data Collection Form when required Sent -   | X |   |     |     |

| Comments: |
|-----------|
|-----------|

Q41 thru Q50 --- No Reporting Records required---

|     |                  | CONSTRUCTION RECORDS   | S | U | N/A | N/C |
|-----|------------------|--|---|---|-----|-----|
| 57. | 192.225          | Do records indicate weld procedures are being qualified in accordance with §192.225?   |   |   | X   |     |
| 58. | 192.227          | Do records indicate adequate qualification of welders?   |   |   | X   |     |
| 59. | 192.241(a)       | Do records indicate that individuals who perform visual inspection of welding are qualified by appropriate training and experience, as required by \$192.241(a)?                     |   |   | X   |     |
| 60. | 192.243(b)(2)    | Do records indicate the qualification of nondestructive testing personnel?   |   |   | X   |     |
| 61. | 192.243(c)       | Do records indicate that NDT implementation is adequate?   |   |   | X   |     |
| 62. | 192.243(f)       | Do records indicate that records are maintained of each pipe/"other than pipe" repair, NDT required record, and (as required by subparts L or M) patrol, survey, inspection or test? |   |   | X   |     |
| 63. | 192.243(f)       | Number of Welds Inspected by NDT   |   |   | X   |     |
| 64. | 192.243(f)       | Number of Welds Rejected   |   |   | X   |     |
| 65. | 192.243(f)       | Disposition of each Weld Rejected  |   |   | X   |     |
| 66. | 480-93-080(1)(b) | Use of testing equipment to record and document essential variables  |   |   | X   |     |
| 67. | 480-93-115(2)    | Test leads on casings (without vents) installed after 9/05/1992  |   |   | X   |     |

S – Satisfactory U – Unsatisfactory N/A – Not Applicable N/C – Not Checked If an item is marked U, N/A, or N/C, an explanation must be included in this report.

|     |                | CONSTRUCTION RECORDS   | S | U | N/A | N/C |
|-----|----------------|--|---|---|-----|-----|
| 68. | 480-93-115(3)  | Sealing ends of casings or conduits on transmission pipelines and main   |   |   | X   |     |
| 69. | 480-93-115(4)  | Sealing ends (nearest building wall) of casings or conduits on services  |   |   | X   |     |
| 70. | 192.303        | Construction Specifications  |   |   | X   |     |
| 71. | 192.325        | Do records indicate pipe is installed with clearances in accordance with §192.325, and (if plastic) installed as to prevent heat damage to the pipe?   |   |   | X   |     |
| 72. | 192.327        | Amount, Location, Cover of each size of pipe installed   |   |   | X   |     |
| 73. | 192.328        | If the pipeline will be operated at the alternative MAOP standard calculated under 192.620 (80% SMYS) does it meet the additional construction requirements for:  • Quality assurance • Girth welds • Depth of cover • Initial strength testing, and; • Interference currents?                 |   |   | X   |     |
| 74. | 480-93-160(1)  | Detailed report filed 45 days prior to construction or replacement of transmission pipelines $\geq$ 100 feet in length   |   |   | X   |     |
| 75. | 480-93-170(3)  | Pressure Tests Performed on new and replacement pipelines  |   |   | X   |     |
| 76. | 480-93-170(10) | Pressure Testing Equipment checked for Accuracy/Intervals (Manufacturers recommendation or operators schedule)   |   |   | X   |     |
| 77. | 480-93-175(1)  | Study prepared and approved prior to moving and lowering of metallic pipelines > 60 psig   |   |   | X   |     |
| 78. | 192.455        | Do records document that each buried or submerged pipeline installed after July 31, 1971, has been protected against external corrosion with a cathodic protection system within 1 year after completion of construction, conversion to service, or becoming jurisdictional onshore gathering? |   |   | X   |     |

#### **Comments:**

Q57 thru Q78 ---- No welding or construction has occurred since last standard audit---

|     |              | OPERATIONS and MAINTENANCE RECORDS   | S | U | N/A | N/( |
|-----|--------------|--|---|---|-----|-----|
| 79. | 192.10       | Do records indicate specific point(s) at which operating responsibility transfers to a producing operator, as applicable? No outer shelf pipelines in area   |   |   | X   |     |
| 80. | 192.14       | Conversion To Service Performance and Records  |   |   |     |     |
| 81. | 192.14(a)(2) | Visual inspection of right of way, aboveground and selected underground segments   |   |   | X   |     |
| 82. | 192.14(a)(3) | Correction of unsafe defects and conditions  |   |   | X   |     |
| 83. | 192.14(a)(4) | Pipeline testing in accordance with Subpart J  |   |   | X   |     |
| 84. | 192.14(b)    | Pipeline records: investigations, tests, repairs, replacements, alterations (life of pipeline)   |   |   | X   |     |
| 85. | 192.16       | Customer Notification (Verification – 90 days – and Elements)  |   |   | X   |     |
| 86. | 192.603(b)   | Procedural Manual Review – Operations and Maintenance ( <b>1 per yr/15 months</b> ) .605(a) <b>Note:</b> Including review of OQ procedures as suggested by PHMSA - ADB-09-03 dated 2/7/09Last reviewed in 2012 | X |   |     |     |
| 87. | 192.603(b)   | Did personnel respond to indications of abnormal operations as required by procedures?  .605(c) (1)Last event was in 2010 – None since   | X |   |     |     |
| 88. | 192.603(b)   | Availability of construction records, maps, operating history to operating personnel .605(b)(3)  | X |   |     |     |
| 89. | 192.603(b)   | Periodic review of personnel work – effectiveness of normal O&M procedures .605(b)(8 Every 90-Days there is a review by CSI  | X |   |     |     |
| 90. | 192.603(b)   | Periodic review of personnel work – effectiveness of abnormal operation procedures .605(c)(4)  | X |   |     |     |

|      |                          | OPERATIONS and MAINTENANCE RECORDS   | S | U | N/A | N/C |
|------|--------------------------|--|---|---|-----|-----|
| 91.  | 192.603(b)               | Do records indicate systematic and routine testing and inspection of pipe-type or bottle-type holders? .605(b)(10)No bottle holders  |   |   | X   |     |
| 92.  |                          | Damage Prevention Program  |   |   |     |     |
| 93.  | 192.603(b)               | List of Current Excavators .614 (c)(1) Checked list  | X |   |     |     |
| 94.  | 192.603(b)               | Notification of Public/Excavators .614 (c)(2   | X |   |     |     |
| 95.  | 192.603(b)               | Notifications of planned excavations. (One -Call Records) .614 (c)(3) Checked locate report  | X |   |     |     |
| 96.  |                          | Provide as follows for inspection of pipelines that an operator has reason to believe could be damaged by excavation activities:   |   |   |     |     |
| 97.  | .614(c)(6)               | Is the inspection done as frequently as necessary during and after the activities to verify the integrity of the pipeline?No Damage Prev. insp. records  |   |   | X   |     |
| 98.  |                          | 2. In the case of blasting, does the inspection include leakage surveys? (required) No blasting  |   |   | X   |     |
| 99.  | 480-93-250(3)            | Are locates are being made within the timeframes required by RCW 19.122? Examine record sampleChecked every locate on record   | X |   |     |     |
| 100. | 195.507(b)               | Are locating and excavating personnel properly <u>qualified</u> in accordance with the operator's Operator Qualification plan and with federal and state requirements?   | X |   |     |     |
| 101. |                          | Does the operator have a quality assurance program in place for monitoring the locating and marking of facilities? Do operators conduct regular field audits of the performance of locators/contractors and take action when necessary? (CGA Best Practices v. 6.0, Best Practice 4-18. Recommended only, not required)  | X |   |     |     |
| 102. |                          | Does operator including performance measures in facility locating services contracts with corresponding and meaningful incentives and penalties?No formal program established but no locating issues so far  | X |   |     |     |
| 103. | PHMSA –<br>State Program | Do locate contractors address performance problems for persons performing locating services through mechanisms such as re-training, process change, or changes in staffing levels?   | X |   |     |     |
| 104. | Evaluation<br>Questions  | Does the operator periodically review the Operator Qualification plan criteria and methods used to qualify personnel to perform locates?   | X |   |     |     |
| 105. |                          | Review operator locating and excavation <u>procedures</u> for compliance with state law and regulationsO&M Manual - Section 5 and Appendix H   | X |   |     |     |
| 106. |                          | Are locates are being made within the timeframes required by state law and regulations? Examine record sample.   | X |   |     |     |
| 107. |                          | Are locating and excavating personnel properly <u>qualified</u> in accordance with the operator's Operator Qualification plan and with federal and state requirements?   | X |   |     |     |
| 108. | 192.709                  | Do records indicate performance of the required study whenever the population along a pipeline increased or there was an indication that the pipe hoop stress was not commensurate with the present class location? 192.605(b)(1) (192.609(a); 192.609(b); 192.609(c); 192.609(d); 192.609(e); 192.609(f))O&M Manual 3.5 of the Classification Surveys F-17 Pipeline Patrol Report | X |   |     |     |
| 109. | 192.605(a)               | Confirmation or revision of MAOP. Final Rule Pub. 10/17/08, eff. 12/22/08611No MAOP revision since 2009  |   |   | X   |     |
| 110. | 192.603(b)               | Prompt and effective response to each type of emergency .615(a)(3) <b>Note:</b> Review operator records of previous accidents and failures including third-party damage and leak responseNo emergencies in system  |   |   | X   |     |
| 111. | 192.615                  | Actions required to be taken by a controller during an emergency in accordance with 192.631. (Amdt. 192-112, 74 FR 63310, December 3, 2009, eff. 2/1/2010)615(a)(11) No Control Rooms  |   |   | X   |     |
| 112. | 192.603(b)               | Location Specific Emergency Plan .615(b)(1)  | X |   |     | L   |
| 113. | 192.603(b)               | Emergency Procedure training, verify effectiveness of training .615(b)(2)Weyerhaeuser has no records of training, run tables or drills since last audit  |   | X |     |     |
| 114. | 192.603(b)               | Employee Emergency activity review, determine if procedures were followed615(b)(3) No emergencies in system  |   |   | X   |     |

|      | OPERATIONS and MAINTENANCE RECORDS |   |   |  |  | N/C |
|------|------------------------------------|---|---|--|--|-----|
| 115. | 192.603(b)                         | Liaison Program with Public Officials .615(c) Member of the LEPC - Physically delivers EPM to officials | X |  |  |     |

| Comments:           |  |  |   |   |     |     |
|---------------------|--|--|---|---|-----|-----|
| - Q81 thru Q85 No c | conversion of service pipelines  |  |   |   |     |     |
|                     |  |  |   |   |     |     |
|                     |  |  |   |   |     |     |
|                     |  |  |   |   |     |     |
|                     |  |  |   |   |     |     |
|                     |  |  |   |   |     |     |
|                     | Public Awarenes  | ss Program .616  | S | U | N/A | N/C |
|                     | Operators in existence on June 20, 2005, must than June 20, 2006. See 192.616(a) and (j) for | have completed their written programs no later exceptions.           |   |   |     |     |
|                     | API RP 1162 Baseline* Reco   | ommended Message Deliveries  |   |   |     |     |
| 402 400 4 )         | Stakeholder Audience (Natural Gas<br>Transmission Line Operators)                            | Baseline Message Frequency<br>(starting from effective date of Plan) |   |   |     |     |
| 192.603(b)          | Residents Along Right-of-Way and Places  | 2 years  |   |   |     |     |
|                     | of Congregation  |  |   |   |     |     |
|                     | Emergency Officials  | Annual   |   |   |     |     |
|                     | Public Officials   | 3 years  |   |   |     |     |
|                     | Excavator and Contractors  | Annual   |   |   |     |     |

|      |            | Stakeholder Audience (Natural Gas<br>Transmission Line Operators)   | Baseline Message Frequency (starting from effective date of Plan)  |   |  |
|------|------------|---|--|---|--|
|      | 192.603(b) | Residents Along Right-of-Way and Places of Congregation   | 2 years  |   |  |
|      |            | Emergency Officials   | Annual   |   |  |
|      |            | Public Officials  | 3 years  |   |  |
|      |            | Excavator and Contractors   | Annual   |   |  |
|      |            | One-Call Centers  | As required of One-Call Center   |   |  |
|      |            | * Refer to API RP 1162 for additional requirer recommendations, supplemental requirements.  |  | _ |  |
| 116. |            | The operator's program must specifically inclusive appropriate government organizations, and per on: .616(d)  (1) Use of a one-call notification system prevention activities;  (2) Possible hazards associated with facility  (3) Physical indications of a possible staken for public safe (5) Procedures to report such an every review was conducted in 2012 / 10 cm. | ade provisions to educate the public, rsons engaged in excavation related activities where prior to excavation and other damage the the unintended release from a gas pipeline the release; ety on the event of a gas pipeline release; and the ent (to the operator)A comprehensive Done every year | X |  |
| 117. | 192.603(b) | Documentation properly and adequately reflect Awareness Program requirements - Stakeholds content, delivery method and frequency, suppletc. (i.e. contact or mailing rosters, postage redocumentation, etc. for emergency responder, program evaluations, etc.)616 (e) & (f)  | er Audience identification, message type and<br>emental enhancements, program evaluations,<br>ceipts, return receipts, audience contact  | X |  |
| 119. |            | The program conducted in English and any off significant number of the population in the open Census data   |  | X |  |
| 120. |            | Do records indicate implementation of a progr<br>continuous improvements based on the finding<br>Section 2.7 Step 11; API RP 1162, Section  | gs? 192.616(i) (192.616(h); API RP 1162,<br>n 8)Review records annually  | X |  |
| 121. |            | Analyzing accidents and failures including lab determine cause and prevention of recurrence <b>Note:</b> Including excavation damage (PHMSA   |  | X |  |

| Comme | nts:          |  |   |   |   |   |
|-------|---------------|--|---|---|---|---|
|       |               |  |   |   |   |   |
|       |               |  |   |   |   |   |
|       |               |  |   |   |   |   |
|       |               |  |   |   |   |   |
|       |               |  |   |   |   |   |
| 122.  | 192.517       | From the review of the results of pressure tests, do the test Pressure test Jul 2009   | t records validate th   | ne pressure test?   | X |   |
| 123.  | .553(b)       | Do records indicate the pressure uprating process was imp<br>192.553?No Uprates since last audit   | plemented per the re  | equirements of  |   | X |
| 124.  | 192.709       | Maximum Allowable Operating Pr   | essure (MAOP)   |   |   |   |
| 125.  |               | Note: If the operator is operating at 80% SMYS with waiver special conditions of the waiver.   | s, the inspector needs  | s to review the   |   |   |
| 126.  | .709          | MAOP cannot exceed the lowest of the following: .619   | No Alternative  | MAOP  |   |   |
| 127.  |               | Design pressure of the weakest element, .619(a)(1) No  | o Alternative MA  | OP  |   | X |
| 128.  |               | The highest actual operating pressure to which the segme years preceding the applicable date in the second column, according to .619(a)(2) after the applicable date in the thir uprated according to subpart K. Amdt 192-102 pub. 3/15/ line related compliance deadlines and additional gather Part 192 including this amendment619(a)(3)  | unless the segment<br>rd column or the seg<br>/06, eff. 04/14/06. <b>F</b>  | was tested in gment was or gathering  |   |   |
|       |               | Pipeline segment  -Onshore gathering line that first became subject to this part (other than §192.612) after April 13, 2006.  Offshore gathering lines   | Pressure date March 15, 2006, or date line becomes subject to this part, whichever is later. July 1, 1976                                     | Test date 5 years preceding applicable date in second column. July 1, 1971                  |   | X |
|       |               | All other pipelines  | July 1, 1970<br>July 1, 1970  | July 1, 1965  |   |   |
| 129.  | .709          | .619(c) The requirements on pressure restrictions in this s instance. An operator may operate a segment of pipeline to considering its operating and maintenance history, at the which the segment was subjected during the 5 years precessecond column of the table in paragraph (a)(3) of this securith §192.611. Amdt 192-102 pub. 3/15/06, eff. 04/14/06 compliance deadlines and additional gathering line regincluding this amendment. | ection do not apply<br>found to be in satisfa-<br>highest actual opera<br>eding the applicable<br>tion. An operator m<br>5. For gathering lin | in the following actory condition, ting pressure to date in the ust still comply ne related |   | X |
| 130.  |               | .620 If the pipeline is designed to the alternative MAOP additional design requirements for:  • General standards  • Fracture control  • Plate and seam quality  • Mill hydrostatic testing  • Coating  • Fittings and flanges  • Compressor stations Final rule pub. 10/1   |   | does it meet the  |   | X |
| 131.  | 480-93-015(1) | Odorization of Gas – Concentrations adequate?  | 17,00, 011. 12/22/00  |   | X |   |
| 132.  | 480-93-015(2) | Monthly Odorant Sniff TestingWell above minimum  |   |   | X |   |
| 133.  | 480-93-015(3) | Prompt action taken to investigate and remediate odorant minimum requirementsNo low reads  |   | meeting the   | X |   |
| 134.  | 480-93-015(4) | Odorant Testing Equipment Calibration/Intervals (Annua Recommendation)Checked calibration for 2013, 20   |   | S   | X |   |

S – Satisfactory U – Unsatisfactory N/A – Not Applicable N/ $\tilde{C}$  – Not Checked If an item is marked U, N/A, or N/C, an explanation must be included in this report.

| 135. | 480-93-124(3) | Pipeline markers attached to bridges or other spans inspected? 1/yr(15 months)Checked all markers | X |  |  |
|------|---------------|---|---|--|--|
| 136. | 480-93-124(4) | Markers reported missing or damaged replaced within 45 days?                                      | X |  |  |

#### **Comments:** O128 thru O130 --- No Alternative MAOP used at facility---137. X 480-93-185(1) Reported gas leaks investigated promptly/graded/record retained 138. Leaks originating from a foreign source reported promptly/notification by mail/record $\mathbf{X}$ 480-93-185(3) retained --- No leak records required---139. X 480-93-187 Gas Leak records - Content --- No leaks in system---140. $\mathbf{X}$ 480-93-188(1) Gas Leak surveys - Coverage Gas detection instruments tested for accuracy/intervals (Mfct rec or monthly not to exceed 141. 480-93-188(2) $\mathbf{X}$ 45 days) --- Checked 2013, 2014, 2015---142. X 480-93-188(3) Leak survey frequency (Refer to Table Below) 1/yr (15 months) **Business Districts (By 6/02/07) High Occupancy Structures** 1/yr (15 months) **Pipelines Operating ≥ 250 psig** 1/yr (15 months) Other Mains: CI, WI, copper, unprotected steel 2/yr (7.5 months) 143. 480-93-188(4)(a) Special leak surveys - Prior to paving or resurfacing, following street alterations or repairs $\mathbf{X}$ 144. Special leak surveys - areas where substructure construction occurs adjacent to $\mathbf{X}$ 480-93-188(4)(b) underground gas facilities, and damage could have occurred 145. $\mathbf{X}$ 480-93-188(4)(c) Special leak surveys - Unstable soil areas where active gas lines could be affected 146. Special leak surveys - areas and at times of unusual activity, such as earthquake, floods, X 480-93-188(4)(d) and explosions Special leak surveys - After third-party excavation damage, operators must perform a gas 147. 480-93-188(4)(e) leak survey to eliminate the possibility of multiple leaks and underground migration into X nearby buildings. 148. Gas survey records: Retention/Content $\mathbf{X}$ 480-93-188(5) 149. $\mathbf{X}$ 480-93-188(6) Leak Survey Program/Self Audits 150. 192.709 Patrolling (Refer to Table Below) .705 --- Checked 2013, 2014, 2015---Class Location At Highway and Railroad Crossings At All Other Places 1 and 2 2/yr (71/2 months) 1/yr (15 months) 4/vr (4½ months) 2/vr (7½ months) 3 4 4/yr ( $4\frac{1}{2}$ months) 4/yr (4½ months) 151. Leak Surveys (Refer to Table Below) .706 ---- Checked 2013, 2014, 192,709 2015---

S – Satisfactory U – Unsatisfactory N/A – Not Applicable N/C – Not Checked If an item is marked U, N/A, or N/C, an explanation must be included in this report.

|      |            | Class Location                            | Required   | Not Exceed              |   |   |
|------|------------|---|--|-------------------------|---|---|
|      |            | 1 and 2                                   | 1/yr   | 15 months               |   |   |
|      |            | 3   | 2/yr   | 7½ months               |   |   |
|      |            | 4   | 4/yr   | 4½ months               |   |   |
|      |            |   |  |                         |   |   |
| 152. | 192.605(b) | Abandoned Pipelines; Underw               | ater Facility Reports .727(g)  |                         |   | X |
| 153. | 192.709    | Compressor Station Relief Dev             | vices – Inspection and Testing (1 per  | yr/15 months) .731(a) - |   | X |
| 154. | 192.709    | Compressor Station Emergenc               | y Shutdown (1 per yr/15 months)  | .731(c)                 |   | X |
| 155. | 192.709    | Compressor Stations – Detecti             | on and Alarms ( <b>Performance Test</b> )  | .736(c)                 |   | X |
| 156. | 192.709    | Pressure Limiting and Regula months) .739 | Pressure Limiting and Regulating Stations – Inspection and Testing intervals (1 per yr/15 months) .739 |                         | X |   |
| 157. | 192.709    | Pressure Limiting and Regulmonths) .743   | ator Stations - Capacity Testing   | or Review (1 per yr/15  | X |   |

#### **Comments:**

-Q143 thru Q147 No special leak surveys required—

-Q152 thru Q157 --- No Compressor Stations in system---

| 158. | 192.709    | Do records indicate proper inspection and partial operation of transmission line <u>valves</u> that may be required during an emergency as required and prompt remedial actions taken if necessary? (1 per yr/15 months) .745                                | X |   |  |
|------|------------|--|---|---|--|
| 159. | 192.709    | Do records document inspections at the required interval of all vaults having a volumetric internal content of 200 cubic feet (5.66 cubic meters) or more that house pressure regulating/limiting equipment? (1 per yr/15 months) .749 –No vaults in system- |   | X |  |
| 160. | 192.603(b) | Do records indicate personnel followed procedures for minimizing the danger of accidental ignition where the presence of gas constituted a hazard of fire or explosion? .751 –No gas releases in system-   |   | X |  |
| 161. | 192.603(b) | Welding – Procedures .225(b)   |   | X |  |
| 162. | 192.603(b) | Welding – Welder Qualification .227/.229   |   | X |  |
| 163. | 192.603(b) | NDT – NDT Personnel Qualification .243(b)(2)   |   | X |  |
| 164. | 192.709    | NDT Records ( <b>Pipeline Life</b> ) .243(f)   |   | X |  |
| 165. | 192.709    | Repair: pipe (Pipeline Life); Other than pipe (5 years) No repairs since last audit  | X |   |  |
| 166. | .807(b)    | Do records document the evaluation and qualifications of individuals performing covered tasks, and can the qualification of individuals performing covered tasks be verified? (Including new construction activities - WAC 480-93-013)                       | X |   |  |
| 167. | 192.905(c) | Periodically examining their transmission line routes for the appearance of newly identified area's (HCA's)  | X |   |  |

#### **Comments:**

S – Satisfactory U – Unsatisfactory N/A – Not Applicable N/C – Not Checked If an item is marked U, N/A, or N/C, an explanation must be included in this report.

Q161 thru Q164 --- No Repairs or construction performed on system---

|      |                  | CORROSION CONTROL RECORDS   | S | U | N/A | N/C |
|------|------------------|---|---|---|-----|-----|
| 168. | 192.453          | CP procedures (system design, installation, operation, and maintenance) must be carried out by qualified personnel.   | X |   |     |     |
| 169. | 192.455(a)(2)    | CP system installed on and operating within 1 yr of completion of pipeline construction (after 7/31/71)Yes  | X |   |     |     |
| 170. | 192.491(c)       | Do records document that each buried or submerged pipeline that has been converted to gas service and was installed after July 31, 1971, has been protected against external corrosion with an adequate coating unless exempted under 192.455(b)?Not a conversion of service system     |   |   | X   |     |
| 171. | 192.491          | Annual Pipe-to-soil Monitoring (1 per yr/15 months) for short sections (10% per year; all in 10 years) .465(a)  | X |   |     |     |
| 172. | 192.491          | Do records indicate the location of all items listed in 192.491(a)?   | X |   |     |     |
| 173. | 192.491          | Examination of Buried Pipe when Exposed .459  | X |   |     |     |
| 174. | 480-93-110(8)    | CP test reading on all exposed facilities where coating has been removedNo pipes were exposed since last inspection-  |   |   | X   |     |
| 175. | 192.491          | Rectifier Monitoring (6 per yr/2½ months) .465(b)   | X |   |     |     |
| 176. | 192.491          | Interference Bond Monitoring – Critical (6 per yr/2½ months) .465(c)No Interference Bonds-  |   |   | X   |     |
| 177. | 192.491          | Interference Bond Monitoring – Non-critical (1 per yr/15 months) .465(c)No Interference Bonds   |   |   | X   |     |
| 178. | 192.491          | Do records adequately document the re-evaluation of buried pipelines with no cathodic protection for areas of active corrosion? (1 per 3 cal yr/39 months) .465(e) All Pipelines have cathodic protection   |   |   | X   |     |
| 179. | 192.491          | Do records adequately document electrical isolation of each buried or submerged pipeline from other metallic structures unless they electrically interconnect and cathodically protect the pipeline and the other structures as a single unit? ( <b>Including Casings</b> ) .467        | X |   |     |     |
| 180. | 480-93-110(2)    | Remedial action taken within 90 days (Up to 30 additional days if other circumstances. Must document) .465(d)   | X |   |     |     |
| 181. | 480-93-110(3)    | CP Test Equipment and Instruments checked for Accuracy/Intervals (Mfct Rec or Opr Sched)  | X |   |     |     |
| 182. | 480-93-110(5)    | Casings inspected/tested annually not to exceed fifteen months  | X |   |     | •   |
| 183. | 480-93-110(5)(a) | Casings w/no test leads installed prior to 9/05/1992. Demonstrate other acceptable test methodsNo Casing w/no test lead records   |   |   | X   |     |
| 184. | 480-93-110(5)(b) | Possible shorted conditions – Perform confirmatory follow-up inspection within 90 days  | X |   |     |     |
| 185. | 480-93-110(5)(c) | Casing shorts cleared when practicalNo Casing shorts foujnd   |   |   | X   | •   |
| 186. | 480-93-110(5)(d) | Shorted conditions leak surveyed within 90 days of discovery. Twice annually/7.5 months   | X |   |     |     |
| 187. | 192.491          | Do records document that pipelines with cathodic protection have <u>electrical test leads</u> <u>installed</u> in accordance with requirements of Subpart I? (192.471; 192.469)   | X |   |     |     |
| 188. | 192.491          | Do records document that the operator has minimized the detrimental effects of stray currents when found? .473 –No stray current issues at facility-  |   |   | X   |     |
| 189. | 192.491          | Do records document if corrosive gas is being transported by pipeline, including the investigation of the corrosive effect of the gas on the pipeline and steps that have been taken to minimize internal corrosion? .475(a)No corrosive gas transported - verified at Williams website |   |   | X   |     |
| 190. | 192.491          | Internal corrosion; Internal surface inspection; Pipe replacement .475(b)   |   |   | X   | 1   |

S – Satisfactory U – Unsatisfactory N/A – Not Applicable N/C – Not Checked If an item is marked U, N/A, or N/C, an explanation must be included in this report.

|      |         | CORROSION CONTROL RECORDS   | S | U | N/A | N/C |
|------|---------|---|---|---|-----|-----|
| 191. | 192.491 | Internal Corrosion; New system design; Evaluation of impact of configuration changes to existing systems . (192.476(b); 192.476(c))                               |   |   | X   |     |
| 192. | 192.491 | Internal Corrosion Control Coupon Monitoring (2 per yr/7½ months) .477  |   |   | X   |     |
| 193. | 192.491 | Atmospheric Corrosion Control Monitoring (1 per 3 cal yr/39 months onshore;<br>1 per yr/15 months offshore) .481  | X |   |     |     |
| 194. | 192.491 | Remedial: Replaced or Repaired Pipe; coated and protected; corrosion evaluation and actions, Records adequate? .483/.485 No repaired or replaced since last audit |   |   | X   |     |

# Comments: Q190 thru Q192 ---No Internal corrosion susceptibility---

|      |                      | PIPELINE INSPECTION (Field)   | S | U | N/A | N/C |
|------|----------------------|---|---|---|-----|-----|
| 195. | 192.161              | Supports and anchors  | X |   |     |     |
| 196. | 192.179              | Valves installed as required? (Proper spacing, Readily accessible, Properly supported, Protection from Tampering/Damage, Blowdown-Discharge/Capacity)                           | X |   |     |     |
| 197. | 480-93-015(1)        | Odorization levels  | X |   |     |     |
| 198. | 192.463(a)           | Levels of Cathodic Protection   | X |   |     |     |
| 199. | 192.465(b)           | Rectifiers  | X |   |     |     |
| 200. | 192.467              | CP - Electrical Isolation (192.467(a), (b), (c))  | X |   |     |     |
| 201. | 192.469              | Test Stations (Sufficient Number)   | X |   |     |     |
| 202. | 192.476              | Systems designed to reduce internal corrosion   | X |   |     |     |
| 203. | 192.479              | Pipeline Components Exposed to the Atmosphere (192.479(a), (b), (c))  | X |   |     |     |
| 204. | 192.481              | Atmospheric Corrosion – monitoring (192.481(b), (c))  | X |   |     |     |
| 205. | 480-93-115(2)        | Casings – Test Leads (Casings w/o vents installed after 9/05/1992)No Casings  | X |   |     |     |
| 206. | 192.605              | Knowledge of Operating Personnel  | X |   |     |     |
| 207. | 192.613; .703        | Pipeline condition, unsatisfactory conditions, hazards, etc. captured and addressed? (192.613(a), (b); 192.703(a), (b), (c))  | X |   |     |     |
| 208. | 480-93-124           | Pipeline Markers: Placed and maintained at above/below ground facilities. Road and railroad crossings (192.707(a))  | X |   |     |     |
| 209. | 192.719              | Pre-pressure Tested Pipe (Markings and Inventory) (192.719(a), (b))   | X |   |     |     |
| 210. | 192.739              | Pressure Limiting and Regulating Devices ( <b>Mechanical</b> ) (spot-check field installed equipment vs. inspection records) (192.739(a), (b); 192.743)                         | X |   |     |     |
| 211. | 192.743              | Pressure Limiting and Regulating Devices (Capacities) (spot-check field installed equipment vs. inspection records) Capacity has never changed                                  | X |   |     |     |
| 212. | 192.745              | Valve Maintenance: Field Inspection and partial operation (192.745(a), (b))   | X |   |     |     |
| 213. | 192.751              | Perform observations of selected locations to verify that adequate steps have been taken by the operator to minimize the potential for accidental ignition. 192.7(a), (b), (c)) | X |   |     |     |
| 214. | 192.801 -<br>192.809 | Operator qualification questions – Refer to OQ Field Inspection Protocol Form   | X |   |     | _   |

#### **Operator Qualification Field Validation**

S – Satisfactory U – Unsatisfactory N/A – Not Applicable N/C – Not Checked If an item is marked U, N/A, or N/C, an explanation must be included in this report.

**Important:** Per PHMSA, the OQ Field Inspection Protocol Form 15 (Rev 6-2012) shall be used by the inspector as part of this standard inspection. When completed, the inspector will upload this information into the PHMSA OQ Database (OQDB) located at <a href="http://primis.phmsa.dot.gov/oqdb/home.oq">http://primis.phmsa.dot.gov/oqdb/home.oq</a> **Date Form Completed/Uploaded?:** 

**Comments:** 

|             | COMPRESSOR STATIONS INSPECTION  (Note: Facilities may be "Grandfathered")  If not located on a platform check here and skip 192.167(c)  THIS PIPELINE HAS NO COMPRESSORS   | S | U | N/A | N/C |
|-------------|--|---|---|-----|-----|
| 192.163 (c) | Main operating floor must have (at least) two (2) separate and unobstructed exits  |   |   | X   |     |
|             | Door latch must open from inside without a key   |   |   | X   |     |
|             | Doors must swing outward   |   |   | X   |     |
| (d)         | Each fence around a compressor station must have (at least) 2 gates or other facilities for emergency exit   |   |   | X   |     |
|             | Each gate located within 200 ft of any compressor plant building must open outward   |   |   | X   |     |
|             | When occupied, the door must be opened from the inside without a key   |   |   | X   |     |
| (e)         | Does the equipment and wiring within compressor stations conform to the <b>National Electric Code</b> , <b>ANSI/NFPA 70?</b>   |   |   | X   |     |
| .165(a)     | If applicable, are there liquid separator(s) on the intake to the compressors?   |   |   | X   |     |
| .165(b)     | Do the liquid separators have a manual means of removing liquids?  |   |   | X   |     |
|             | If slugs of liquid could be carried into the compressors, are there automatic dumps on the separators, Automatic compressor shutdown devices, or high liquid level alarms? |   |   | X   |     |
| .167(a)     | ESD system must:   |   |   |     |     |
|             | - Discharge blowdown gas to a safe location  |   |   | X   |     |
|             | - Block and blowdown the gas in the station  |   |   | X   |     |
|             | - Shut down gas compressing equipment, gas fires, electrical facilities in compressor building and near gas headers  |   |   | X   |     |
|             | - Maintain necessary electrical circuits for emergency lighting and circuits needed to protect equipment from damage   |   |   | X   |     |
|             | ESD system must be operable from at least two locations, each of which is:   |   |   |     |     |

|          | COMPRESSOR STATIONS INSPECTION  (Note: Facilities may be "Grandfathered")  If not located on a platform check here and skip 192.167(c)  THIS PIPELINE HAS NO COMPRESSORS         | S | U | N/A | N/C |
|----------|--|---|---|-----|-----|
|          | - Outside the gas area of the station  |   |   | X   |     |
|          | - Not more than 500 feet from the limits of the station  |   |   | X   |     |
|          | - ESD switches near emergency exits?   |   |   | X   |     |
| .167 (b) | For stations supplying gas directly to distribution systems, is the ESD system configured so that the LDC will not be shut down if the ESD is activated?                         |   |   | X   |     |
| .167(c)  | Are ESDs on platforms designed to actuate automatically by   |   |   |     |     |
|          | - For unattended compressor stations, when:  | _ |   |     |     |
|          | The gas pressure equals MAOP plus 15%?   |   |   | X   |     |
|          | An uncontrolled fire occurs on the platform?   |   |   | X   |     |
|          | - For compressor station in a building, when   |   |   |     |     |
|          | An uncontrolled fire occurs in the building?   |   |   | X   |     |
|          | <ul> <li>Gas in air reaches 50% or more of LEL in a building with a source of ignition (facility conforming to<br/>NEC Class 1, Group D is not a source of ignition)?</li> </ul> |   |   | X   |     |
| .171(a)  | Does the compressor station have adequate fire protection facilities? If fire pumps are used, they must not be affected by the ESD system.                                       |   |   | X   |     |
| (b)      | Do the compressor station prime movers (other than electrical movers) have over-speed shutdown?  |   |   | X   |     |
| (c)      | Do the compressor units alarm or shutdown in the event of inadequate cooling or lubrication of the unit(s)?  |   |   | X   |     |
| (d)      | Are the gas compressor units equipped to automatically stop fuel flow and vent the engine if the engine is stopped for any reason?   |   |   | X   |     |
| (e)      | Are the mufflers equipped with vents to vent any trapped gas?  |   |   | X   |     |
| .173     | Is each compressor station building adequately ventilated?   |   |   | X   |     |
| .457     | Is all buried piping cathodically protected?   |   |   | X   |     |
| .481     | Atmospheric corrosion control of aboveground facilities 192.481(b), (c); 192.479(a), (b), (c))   |   |   | X   |     |
| .605     | Does the operator have procedures for the start-up and shut-down of the station and/or compressor units? 192.605(b)(5)   |   |   | X   |     |
|          | Are facility maps current/up-to-date? 192.605(b)(3)  |   |   | X   |     |

S – Satisfactory U – Unsatisfactory N/A – Not Applicable N/C – Not Checked If an item is marked U, N/A, or N/C, an explanation must be included in this report.

|               | COMPRESSOR STATIONS INSPECTION  (Note: Facilities may be "Grandfathered")  If not located on a platform check here and skip 192.167(c)  THIS PIPELINE HAS NO COMPRESSORS | S | U | N/A | N/C |
|---------------|--|---|---|-----|-----|
| .616          | Public Awareness Program effectiveness - Visit identified stakeholders as part of field inspection routine   |   |   | X   |     |
| .605; .615(b) | Emergency Plan for the station on site?  |   |   | X   |     |
| .707          | Markers  |   |   | X   |     |
| .199/.731     | Are pressure relief/limiting devices inside a compressor station designed, installed, and inspected properly? (192.199, 192.731(a), (b), (c))                            |   |   | X   |     |
| .735(a), (b)  | Are combustible materials in quantities exceeding normal daily usage, stored a safe distance from the compressor building?   |   |   | X   |     |
|               | Are aboveground oil or gasoline storage tanks protected in accordance with NFPA standard No. 30?   |   |   | X   |     |
| .736(a), (b)  | Have adequate gas detection and alarm systems been installed in selected applicable compressor buildings?  |   |   | X   |     |

| Comments:<br>THIS PIPELINE HAS NO COMPRESSORS |  |
|---|--|
|   |  |

#### Alternative Maximum Allowable Operating Pressure THIS PIPELINE DOES NOT USE ALTERNATIVE MAOP

For additional guidance refer to <a href="http://primis.phmsa.dot.gov/maop/faqs.htm">http://primis.phmsa.dot.gov/maop/faqs.htm</a> For Additional guidance see the FAQs at <a href="http://primis.phmsa.dot.gov/maop/faqs.htm">http://primis.phmsa.dot.gov/maop/faqs.htm</a>

| 192.620 | Alternative MAOP Procedures and Verifications   | S | U | N/A | N/C |
|---------|---|---|---|-----|-----|
|         | The alternative MAOP is calculated by using different factors in the same formulas used for calculating MAOP in \$192.619. In determining the alternative design pressure under \$192.105 use a design factor determined in accordance with \$192.111(b), (c), or (d), or, if none of these apply in accordance with: |   |   |     |     |
|         | Class Location Alternative Design Factor (F)  1 0.80 2 0.67 3 0.56  |   |   |     |     |
| .620(a) | (1) Establish alternative MAOP commensurate with class location – no class 4  |   |   | X   |     |
|         | (2) MAOP cannot exceed the lowest of the following:   |   |   |     |     |
|         | (i) Design pressure of the weakest element  |   |   | X   |     |

| 192.620 |     | Alternative MAOP Procedures and Verifications  | S | U | N/A | N/C |
|---------|-----|--|---|---|-----|-----|
|         |     | (ii) Test pressure divided by applicable factor  |   |   | X   |     |
|         | (2) | Pipeline constructed of steel pipe meeting additional requirements in §192.112.                  |   |   | X   |     |
|         | (3) | SCADA system with remote monitoring and control  |   |   | X   |     |
| .620(b) | (4) | Additional construction requirements described in §192.328                                       |   |   | X   |     |
|         | (5) | No mechanical couplings  |   |   | X   |     |
|         | (6) | No failures indicative of systemic material fault – if previously operated at lower MAOP         |   |   | X   |     |
|         | (7) | 95% of girth welds have NDT  |   |   | X   |     |
|         | (1) | PHMSA notified 180 days before operating at alternative MAOP                                     |   |   | X   |     |
|         | (2) | Senior Executive signatures and copy to PHMSA  |   |   | X   |     |
| .620(c) | (4) | Strength test per §192.505 or certify previous strength test                                     |   |   | X   |     |
|         | (6) | Construction tasks treated as covered tasks for Operator Qualification                           |   |   | X   |     |
|         | (7) | Records maintained for life of system  |   |   | X   |     |
|         | (8) | Class location change anomaly remediations   |   |   | X   |     |
|         | (1) | Threat matrix developed consistent with §192.917   |   |   | X   |     |
|         | (2) | Recalculate the potential impact circle per §192.903 and implement public education per §192.616 |   |   | X   |     |
|         | (3) | Responding to an emergency in an HCA   |   |   |     |     |
|         |     | (i) Identify HCAs using larger impact circle   |   |   | X   |     |
| 620(d)  |     | (ii) Check personnel response times  |   |   | X   |     |
|         |     | (iii) Verify remote valve abilities  |   |   | X   |     |
|         |     | (iv) Verify line break valve control system  |   |   | X   |     |
|         | (4) | Protect the right-of-way:  |   |   |     |     |
|         |     | (i) ROW patrols 12 per year not to exceed 45 days  |   |   | X   |     |

| 192.620 | Alternative MAOP Procedures and Verifications                         | S                    | U | N/A | N/C |
|---------|---|----------------------|---|-----|-----|
|         | (ii) Plan to identify and mitigate unstable soil                      |                      |   | X   |     |
|         | (iii) Replace loss of cover if needed                                 |                      |   | X   |     |
|         | (iv) Use line-of-sight markers per §192.707                           |                      |   | X   |     |
|         | (v) Review damage prevention program in light of national consensu    | ıs practices         |   | X   |     |
|         | (vi) ROW management plan to protect against excavation activities     |                      |   | X   |     |
|         | (5) Control Internal Corrosion:                                       |                      | 1 |     |     |
|         | (i) Program to monitor gas constituents                               |                      | Т | X   |     |
|         | (ii) Filter separators if needed                                      |                      |   | X   |     |
|         | (iii) Gas Monitoring equipment used                                   |                      |   | X   |     |
|         | (iv) Cleaning pigs, inhibitors, and sample accumulated liquids        |                      |   |     |     |
| .620(d) | (v) Limit CO2, H2S, and water in the gas stream                       |                      |   | X   |     |
|         | (vi) Quarterly program review based on monitoring results             |                      |   | X   |     |
|         | (6) (i) Control interference that can impact external corrosion       |                      |   | X   |     |
|         | (ii) Survey to address interference currents and remedial actions     |                      |   | X   |     |
|         | (7) Confirm external corrosion control through indirect assessment    |                      |   | X   |     |
|         | (i) Assess adequacy of CIS and perform DCVG or ACVG within 6          | months               | + |     |     |
|         | (ii) Remediate damage with IR drop > 35%                              |                      | Π | X   |     |
|         | (iii) Integrate internal inspection results with indirect assessment  |                      |   | X   |     |
|         | (iv) Periodic assessments for HCAs                                    |                      |   | X   |     |
|         | (A-C) Close interval surveys, test stations at ½ mile intervals, an   | nd integrate results |   |     |     |
|         | (8) Cathodic Protection   |                      | Π | X   |     |
|         | (i) Complete remediations within 6 months of failed reading           |                      | _ | ·   |     |
|         | (ii) Confirm restoration by a close interval survey                   |                      |   | X   |     |
|         | (iii) Cathodic protection system operational within 12 months of cons | struction completion |   | X   |     |

| )      | Alternative MAOP Procedures and Verifications  | S | U | N/A | N/C |
|--------|--|---|---|-----|-----|
| (9)    | Baseline assessment of integrity   |   |   | X   |     |
|        | (i)(A) Geometry tool run within 6 months of service  |   |   |     |     |
|        | (i)(B) High resolution MFL tool run within 3 years of service  |   |   | X   |     |
|        | (ii) Geometry and MFL tool 2 years prior to raising pressure for existing lines                                    |   |   | X   |     |
|        | (iii) If short portions cannot accommodate tools, use direct assessment per §192.925, 927, 929 or pressure testing |   |   | X   |     |
| (10)   | Periodic integrity assessments   |   |   | X   |     |
|        | (i) Frequency for assessments determined as if all segments covered by Subpart O                                   |   |   |     |     |
| testin | (ii) Inspect using MFL tool or direct assessment per §192.925, 927, 929 or pressure g.                             |   |   | X   |     |
| (11)   | Repairs  |   |   | X   |     |
|        | (i)(A) Use of the most conservative calculation for anomaly remaining strength                                     |   |   |     |     |
|        | (B) Tool tolerances taken into consideration   |   |   | X   |     |
|        | (ii) Immediate repairs for:  |   |   | X   |     |
|        | (A) Dents meeting 309(b) criteria  |   |   |     |     |
|        | (B) Defects meeting immediate criteria in §192.933(d)  |   |   | X   |     |
|        | (C) Calculated failure pressure ratio less than 1.25 for .67 design factor   |   |   | X   |     |
|        | (D) Calculated failure pressure ratio less than 1.4 for .56 design factor  |   |   | X   |     |
|        | (iii) Repairs within 1 year for:   |   |   | X   |     |
|        | (A) Defects meeting 1 year criteria in 933(d)  |   |   |     |     |
|        | (B) Calculated failure pressure ratio less than 1.25 for .80 design factor   |   |   | X   |     |
|        | (C) Calculated failure pressure ratio less than 1.50 for .67 design factor   |   |   | X   |     |
|        | (D) Calculated failure pressure ratio less than 1.80 for .56 design factor   |   |   | X   |     |
|        | (iv) Evaluate defect growth rate for anomalies with > 1 year repair interval and set repair interval               |   |   | X   |     |
| (1)    | Provide overpressure protection to a max of 104% MAOP  |   |   | X   |     |
| Does   | the AMAOP process include overpressure protection requirements?  |   |   | X   |     |

S – Satisfactory U – Unsatisfactory N/A – Not Applicable N/C – Not Checked If an item is marked U, N/A, or N/C, an explanation must be included in this report.

| 192.620 | Alternative MAOP Procedures and Verifications                           | S | U | N/A | N/C |
|---------|---|---|---|-----|-----|
|         | Do records indicate that overpressure protection requirements were met? |   |   | X   |     |
|         |   |   |   |     |     |
|         |   |   |   |     |     |

| Comments: THIS PIPELINE DOES NOT USE ALTERNATIVE MAOP |  |
|---|--|
|   |  |
|   |  |

Recent Gas Pipeline Safety Advisory Bulletins: (Last 2 years)

| <u>Number</u> | <u>Date</u> | Subject   |
|---------------|-------------|---|
| ADB-2013-07   | July 12, 13 | Potential for Damage to Pipeline Facilities Caused by Flooding                  |
| ADB-2012-10   | Dec 5, 12   | Using Meaningful Metrics in Conducting Integrity Management Program Evaluations |

S – Satisfactory U – Unsatisfactory N/A – Not Applicable N/C – Not Checked If an item is marked U, N/A, or N/C, an explanation must be included in this report.

| ADB-2012-09 | Oct 11, 12 | Communication During Emergency Situations   |
|-------------|------------|---|
| ADB-2012-08 | Jul 31, 12 | Inspection and Protection of Pipeline Facilities After Railway Accidents  |
| ADB-12-07   | Jun 11, 12 | Mechanical Fitting Failure Reports  |
| ADB-12-06   | May 7, 12  | Verification of Records establishing MAOP and MOP   |
| ADB-12-05   | Mar 23, 12 | Cast Iron Pipe (Supplementary Advisory Bulletin)  |
| ADB -12-04  | Mar 21, 12 | Implementation of the National Registry of Pipeline and Liquefied Natural Gas<br>Operators                            |
| ADB-12-03   | Mar 6, 12  | Notice to Operators of Driscopipe 8000 High Density Polyethylene Pipe of the  |
| ADB-11-05   | Sep 1, 11  | Potential for Material Degradation<br>Potential for Damage to Pipeline Facilities Caused by the Passage of Hurricanes |
| ADB-11-04   | Jul 27, 11 | Potential for damage to pipeline facilities caused by severe flooding.  |

For more PHMSA Advisory Bulletins, go to <a href="http://phmsa.dot.gov/pipeline/regs/advisory-bulletin">http://phmsa.dot.gov/pipeline/regs/advisory-bulletin</a>

| Comments: |
|-----------|
|           |
|           |
|           |
|           |
|           |
|           |
|           |